



## Cargador rápido GAL 18 V-160 AS

Tiempos de carga cortos gracias a la elevada corriente de carga de 16 amperios, el modo de carga Power Boost, la refrigeración de aire activa y la gestión de carga controlada por proceso. Con indicador de nivel de carga y dispositivo para montaje en la pared. Para todos los equipos a batería con alojamiento para la batería AMPShare o Bosch Professional de 18 V. Tiempos de carga (80 % de la capacidad máx.): GBA 18 V 2.0 Ah: 15 min., GBA 18 V 4.0 Ah: 16 min., GBA 18 V 5.0 Ah: 20 min., ProCORE 18 V 4.0 Ah: 32 min., ProCORE 18 V 8.0 Ah: 32 min., ProCORE 18 V 12.0 Ah: 36 min.

. N.º pedido: 9 26 04 339 01 0

Adaptable para las siguientes máquinas

### Taladro atornillador con acumulador

- > ABS 18 Q AS
- > ASCM 18 QSW AS
- > ASCM 18-4 QM AS
- > ASB 18 Q AS
- > ASCM 18-4 QMP AS
- > ABS 18 Q AS Set 5 Ah
- > ASCM 18 QSW AS Set 5 Ah
- > ASCM 18-4 QM AS Set 5 Ah
- > ASB 18 Q AS Set 5 Ah
- > ASCM 18-4 QMP AS Set 5 Ah
- > ASCM 18-4 QM AS Universal-lean-top Set
- > ASCM 18-4 QM AS Metal Advanced Top Set
- > ASCM 18-4 QM AS Metal Advanced Set
- > ASCM18-4 QM AS QuickIN Set

### Llave de impacto a batería

- > ASCD 18-300 W2 AS
- > ASCD 18-300 W2 AS Ready to-use-top Set
- > ASCD 18-300 W2 AS Ready-to-use Set
- > ASCD 18-300 W2 AS Impact-tapping-top Set



# FEIN

- > ASCD 18-300 W2 AS Impact-tapping Set 5 Ah
- > ASCD 18-200 W4 AS Set 5 Ah
- > ASCD 18-1000 W34 AS
- > ASCD 18-300 W2 AS Set

## Universal

- > AKBU 35 PMQ AS
- > AKBU 35 PMQW AS
- > AKBU 35 PMQW 18 V AS Set 2x 8 Ah
- > AKBU 35 PMQW 18 V AS Set 1x 12 Ah
- > AKBU 35 PMQW AS Construction-Site Set 3/4 in Weldon / HSS NOVA 50
- > AKBU 35 PMQW 18 V AS Construction-Site 1x 12 Ah Set 3/4 in Weldon / HSS NOVA 50
- > AKBU 35 PMQW 18 V AS Construction-Site 2x 8 Ah Set 3/4 in Weldon / HSS NOVA 50

## Amoladora angular (Premium)

- > CCG 18-115-12 AS
- > CCG 18-125-12 PD AS
- > CCG 18-125-12 PD AS Set ProCore
- > CCG 18-115-12 PD-SEC AS
- > CCG 18-115-12 PD-SEC AS Set ProCore
- > CCG 18-125-12 PD-SEC AS
- > CCG 18-125-12 PD-SEC Set 8Ah ProCORE AS

## Biselado

- > AKFH 18-5 AS
- > Set básico para biselado AKFH 18-5 AS con 1
- > batería 8 Ah ProCore
- > Set básico para biselado AKFH 18-5 AS con 2
- > baterías 8 Ah ProCore
- > Set básico para biselado AKFH 18-5 AS



# FEIN

## Rectificadora recta

- > AGSZ 18-280 BL AS
- > AGSZ 18-280 LBL AS
- > AGSZ 18-90 LBL AS

## Taladro percutor a batería

- > ABH 18-26 AS
- > ABH 18-26 AS Set 5 Ah

## Amoladora angular (Universal)

- > CCG 18-125-15 AS
- > CCG 18-125-7 AS

## Sierra circular sin cable

- > F-IRON Cut 57 AS
- > F-IRON Cut 57 AS Set 2 x 8 Ah

## Sierra de cinta sin cable

- > ABAS 18-63 AS
- > ABAS 18-63 AS Set 2 x 8 Ah